


Equipment recall

2006

Issue

Petzl have announced the recall of 2 types of new karabiners which have been on sale since February 2006. The recall is because of defects with a new metal sleeve on the Am'D Ball-Lock (M34 BL) and the William Ball-Lock (M36 BL) which replaced the older nylon sleeve.

Outcome

Take used or unused stock to your point of purchase for a full credit from Petzl. Further info available from [Lyon](#) 

[1]

Link URLs in this page

1. Lyon
<http://www.lyon.co.uk/>